



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
July 19, 2007

Supervisor 10074

Mine Name: Amis #1

Operator Name: Quality Building Stone, Inc.

Permit number: S/049/038

Inspection Date: July 17, 2007

Time: 10:30 am

Inspector(s): Steve Demczak, Dan Smith, Lynn Kunzler, DOGM

Other Participants: None

Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

There has been activity at this site recently. There was even a chain and cable attached to a large rock on the highwall, apparently to pull the rock down. The disturbed area is approaching the 5- acre limit for a small mining operation. According to DOGM records, the operator has not yet provided a reclamation surety for this site. There is no signs of erosion problems. No trash or deleterious materials were noted.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Since operations have continued without providing the requisite reclamation surety and reclamation contract, Enforcement action should be taken.

Inspector's Signature 474

LK:pb

O:\M049-Utah\S0490038-Amis\inspections\Insp-07172007.doc